NOAFS# Natalia Vasquez



March 28, 2018

#### CERTIFIED MAIL

Director, Air Protection Division EPA Region III Mail Code 3AP00 1650 Arch Street Philadelphia, PA 19103-2029

MAR 29 2018

Subject:

JKLM Energy, LLC.

Sweden Valley Well Site 102

NSPS Subpart OOOOa Annual Report

Dear Director,

JKLM Energy, LLC. (JKLM) is submitting the NSPS Subpart OOOOa Annual Report for Sweden Valley 102 well site in Summit Township, Potter County, Pennsylvania, in accordance with 40 Code of Federal Regulations (CFR) §60.5420a(b). The annual report is due no later than the same date each year as the initial annual report, which was submitted on April 6, 2017.

This Annual Report includes applicable information of the items required under 40 CFR §60.5420a(b).

- General Information
- Well Information
- Centrifugal Compressor Information
- Reciprocating Compressor Information
- Pneumatic Controller Information
- Storage Vessel Information
- Fugitive Emissions Components Information
- Pneumatic Pump Information
- Performance Test Information
- Combustion Control Device Information
- Closed Vent System Certification



#### March 28, 2018

If you have any questions or concerns, please contact me at 724-935-9815 or <a href="mailto:jharrick@emslp.com">jharrick@emslp.com</a> or Allison Devine at 412-858-1566 or <a href="mailto:allison.devine@aptim.com">allison.devine@aptim.com</a>, and we will provide any clarification or additional information.

Sincerely,

Joseph M. Harrick

General Manager, Environmental Safety and Health

Cc: Commonwealth of Pennsylvania, Department of Environmental Protection

#### NSPS SUBPART OOOOa ANNUAL REPORT

#### **SWEDEN VALLEY 102**

Potter County, Pennsylvania

March 2018

Prepared for:



JKLM Energy, LLC 2200 Georgetowne Drive Suite 500 Sewickley, Pennsylvania 15143

Prepared by:



Aptim Environmental & Infrastructure, Inc. 500 Penn Center Boulevard Suite 1000 Pittsburgh, Pennsylvania 15235

## **Table of Contents**

1.	General Information	. 1
2.	Well Information	
3.	Centrifugal Compressor	. 1
4.	Reciprocating Compressor	
5.	Pneumatic Controller	. 1
6.	Storage Vessel	. 2
7.1	Fugitive Emissions Components – Survey 1	. 2
7.2	Fugitive Emissions Components – Survey 2	. 2
8.	Pneumatic Pump	. 3
9.	Closed Vent System Certification	. 3

## **List of Attachments**

Attachment 1 Certification Statement

1. General Information [40 CFR 60.5420a(b)(1)]	
Requirement	Response
Company Name [(b)(1)(i)]	JKLM Energy, LLC
Facility Site Name [(b)(1)(i)]	Sweden Valley 102
US Well ID [(b)(1)(i)]	37-105-21850-00-00
Location [(b)(1)(i)]  • Address	See Site Location Description and Latitude/Longitude Coordinates below.
If address not available:  • Site Location Description	Facility is located off of Cherry Springs Road (Highway 44) about 5 miles south of the intersection of Cherry Springs Road with East 2 <sup>nd</sup> Street (Highway 6) in Potter County near Summit Township municipality.
<ul> <li>Lat/Long Coordinates (NAD 1983)</li> </ul>	41.71724, -77.89994
Identification of each affected facility included in report [(b)(1)(ii)]	Fugitive Components at the Well Site
Reporting Period [(b)(1)(iii)]	
Beginning Date	January 9, 2017
End Date	January 9, 2018
Certification Statement [(b)(1)(iv)]	See Attachment 1

2. Well Information [40 CFR 60.5420a(b)(2)]	
Requirement	Response
	Not Applicable. No well completion operations during the compliance period.

3. Centrifugal Compressor	
Requirement	Response
	Not Applicable. No centrifugal compressors are located at this site.

4. Reciprocating Comp [40 CFR 60.5420a(b)(4)]	ressor
Requirement	Response
<u> </u>	Not Applicable. No reciprocating compressors are located at this site.

5. Pneumatic Controller [40 CFR 60.5420a(b)(5)]	
Requirement	Response
	Not Applicable. No applicable pneumatic controllers are located at this site.

6. Storage Vessel	
Requirement	Response
	Not Applicable. No applicable storage vessels are located at this site.

Requirement	Response
<ul><li>Date of Survey [(b)(7)(i)]</li></ul>	May 23, 2017
<ul><li>Time of Survey [(b)(7)(ii)]</li></ul>	The value of the
<ul><li>Start Time</li></ul>	3:31 pm
∘ End Time	4:33 pm
<ul> <li>Name of operator(s) performing survey.</li> </ul>	Ryan J. Flanagan. Certified OGI Thermographer
If using OGI, note the training and	through June 15, 2022, by Infrared Training Center with
experience of the operator. [(b)(7)(iii)]	four years of LDAR experience.
<ul> <li>Ambient temperature, sky conditions, and maximum wind speed [(b)(7)(iv)]</li> </ul>	73.7°F; clear skies; 1.1 mph winds
<ul> <li>Monitoring instrument [(b)(7)(v)]</li> </ul>	FLIR Infrared Camera Model GF320
<ul> <li>Any deviations from the monitoring plan [(b)(7)(vi)]</li> </ul>	No
<ul> <li>Number and type of components where fugitive emissions were detected [(b)(7)(vii)]</li> </ul>	(1) One Valve; (2) Others
<ul> <li>Number and type of components that were not repaired [(b)(7)(viii)]</li> </ul>	(0) Zero
<ul> <li>Number and type of difficult-to-monitor and unsafe-to-monitor components monitored [(b)(7)(ix)]</li> </ul>	Not Applicable
<ul> <li>Date of successful repair of components [(b)(7)(x)]</li> </ul>	May 23, 2017; June 22, 2017
<ul> <li>Number and type of components placed on delay of repair and explanation for delay [(b)(7)(xi)]</li> </ul>	(0) Zero
<ul> <li>Type of instrument used to resurvey repaired components that could not be repaired during initial finding [(b)(7)(xii)]</li> </ul>	FLIR Infrared Camera Model GF320

7.2 Fugitive Emissions Components – Survey 2  [40 CFR 60.5420a(b)(7)]		
Requirement Response		
<ul><li>Date of Survey [(b)(7)(i)]</li></ul>	October 10, 2017	
Time of Survey [(b)(7)(ii)]		
o Start Time	1:34 pm	
○ End Time	2:32 pm	
<ul> <li>Name of operator(s) performing survey.</li> </ul>	Ryan J. Flanagan. Certified OGI Thermographer	
If using OGI, note the training and	through June 15, 2022, by Infrared Training Center with	
experience of the operator. [(b)(7)(iii)]	four years of LDAR experience.	

0 CFR 60.5420a(b)(7)]	Response
Requirement	75.1°F; overcast skies; 5.1 mph winds
<ul> <li>Ambient temperature, sky conditions, and maximum wind speed [(b)(7)(iv)]</li> </ul>	
Monitoring instrument [(b)(7)(v)]	FLIR Infrared Camera Model GF320
Any deviations from the monitoring	No
plan [(b)(7)(vi)]  Number and type of components where fugitive emissions were detected [(b)(7)(vii)]	(1) One Other
Number and type of components that were not repaired [(b)(7)(viii)]	(0) Zero
<ul> <li>Number and type of difficult-to-monitor and unsafe-to-monitor components monitored [(b)(7)(ix)]</li> </ul>	Not Applicable
Date of successful repair of components [(b)(7)(x)]	October 10, 2017
Number and type of components placed on delay of repair and explanation for delay [(b)(7)(xi)]	(0) Zero
<ul> <li>Type of instrument used to resurvey repaired components that could not be repaired during initial finding [(b)(7)(xii)]</li> </ul>	Not Applicable

3. Pneumatic Pump 40 CFR 60.5420a(b)(8)]	
[40 CFR 60.5420a(b)(0)]	Response
Requirement	Not Applicable. No applicable pneumatic pumps are located at this site.

9. Closed Vent System	Certification
[40 CFR 60.5420a(b)(12)] Requirement	Response
	Not Applicable. No closed vent systems are located at this site.

## Attachment 1

**Certification Statement** 

# 40 CFR SUBPART OOOOa ANNUAL REPORT CERTIFICATION STATEMENT

40 CFR 60.5420a(b)(1)(iv)

Based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Joseph M. Harrick
Printed Name
General Manager, Environmental Health and Safety
Title
Signature y. Harring
March 28, 2018

Date